

GREG BELL Lieutenant Governor

## State of Utah

#### DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Representatives Present During the Inspection:				
OGM	Pete Hess			

# **Inspection Report**

Permit Number:	C0070033		
Inspection Type:	PARTIAL		
Inspection Date:	Thursday, September 30, 2010		
Start Date/Time:	9/30/2010 8:25:00 AM		
End Date/Time:	9/30/2010 9:05:00 AM		
Last Inspection:	Thursday, September 09, 2010		

Inspector: <u>Pete Hess</u>, Weather: <u>Clear</u>, 70s F.

InspectionID Report Number: 2502

Accepted by: jhelfric 9/28/2010

Permitee: ANDALEX RESOURCES INC Operator: ANDALEX RESOURCES INC

Site: WILDCAT LOADOUT

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages		Mineral Ownership	Types of Operations		
100.00 Tota	I Permitted	<b>✓</b> Federal	Underground		
78.45 <b>Tota</b>	l Disturbed	☐ State	Surface		
	Phase I	☐ County	<b>✓</b> Loadout		
5	Phase II	☐ Fee	<b>✓</b> Processing		
F	Phase III	☐ Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Andalex Resources, Inc., a subsidiary of UtahAmerican Energy, notified the Division on September 10,2010 that they had temporarily ceased operation of the Wildcat Loadout. Under contractual terms with the Intermountain Power Agency / Los Angeles Department of Water and Power, Andalex is now preparing for the legal transfer of ownership of the facility to Intermountain Power. The Division received this notification on September 13, 2010. To date, no official submittal has been made to the Division for the transfer of this permit.

Inspector's Signature:

Lites Dess

Date

Thursday, September 2010

Pete Hess,

Inspector ID Number: 46

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Thursday, September 30, 2010

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓			
3.	Topsoil	V			
4.a	Hydrologic Balance: Diversions	<b>~</b>			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		<b>✓</b>	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		<b>Y</b>	
4.d	Hydrologic Balance: Water Monitoring	<b>✓</b>		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		Y		
6.	Disposal of Excess Spoil, Fills, Benches		V		
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		✓	
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage		V		
11.	Contemporaneous Reclamation		V		
12.	Backfilling And Grading		V		
13.	Revegetation				
14.	Subsidence Control		V		
15.	Cessation of Operations	V		V	
16.	a Roads: Construction, Maintenance, Surfacing	V			
16.	Roads: Drainage Controls	V			
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22	Other				

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Thursday, September 30, 2010

Page 3 of 3

## 4.b Hydrologic Balance: Sediment Ponds and Impoundments

All ponds are dry; all inlet ditches and outfalls are capable of functioning as designed.

### 4.c Hydrologic Balance: Other Sediment Control Measures

The Permittee intends to initiate straw application, discing and seeding of the coal fines removal area on October 4, 2010.

## 4.d Hydrologic Balance: Water Monitoring

There was no flow in Wildcat Wash. All areas are dry.

## 7. Coal Mine Waste, Refuse Piles, Impoundments

The pile has been graded and compacted. Noncoal waste is not visible. No water is impounded on the pile.

#### 15. Cessation of Operations

This site is in temporary cessation status as of September 10, 2010. All gates are locked and truck grizzleys are blocked. Power has been de-energized. The north door on the scale house trailer had been kicked in, allowing unauthorized access.